

FIG. 1A




FIG. 1B




FIG. 2A




FIG. 2B




FIG. 3




FIG. 4A






FIG. 4B



Jitter 12.6%
 Error rate : Measurement is impossible because of large asymmetry

FIG. 5



Jitter 13.4%
 Error rate : 4×10^{-6}

FIG. 6




FIG. 7B




FIG. 8




FIG. 9